Serial No. 10/088,206

 \bigcirc

Group Art Unit: 2859 Examiner: Gail Kaplan Verbitsky

ABSTRACT

The method and device to monitor the wear of a rapier band of a rapier loom is based on analyzing the temperature of the rapier band and/or of a component in contact with the rapier band as a characteristic value of rapier band wear.